



**Experience with CRYOGENIC Vessel**

*New*

JOB NO	DESCRIPTION	OWNER	PROJECT_NAME	PURCHASER	QUANTITY	WEIGHT (ton)	Material	Capacity (l) ea.	COMMENCEMENT	COMPLETED	SCOPE of work			
											DESIGN	MATERIAL	SHOP	FIELD
12-7633	FABRICATION CRYOGENIC TANK VIE 310,000 LT x 560 kPa	British Oxygen Company (BOC)	Karrantha/Australia	PIONEER CRYOGENICS PTY LTD.	1 UNIT	81.10	A240 TP304/SS400	310,000	22-Mar-12	30-Oct-12	-	X	X	-
12-7705	FABRICATION CRYOGENIC TANK VIE350000L x 250 kPa	British Oxygen Company (BOC)	Glenbrook/Newzealand	PIONEER CRYOGENICS PTY LTD.	6 UNITS	540.00	A240 TP304/SS400	350,000	08-Jun-12	31-Aug-13	-	X	X	-

*Service*

JOB NO	DESCRIPTION	OWNER	PROJECT_NAME	PURCHASER	QUANTITY	WEIGHT (ton)	Material	Capacity (l) ea.	COMMENCEMENT	COMPLETED	SCOPE of work			
											DESIGN	MATERIAL	SHOP	FIELD
13-8027	Repairing of CRYOGENIC tanl VIE310000L X 560 kPa	PIONEER CRYOGENICS PTY LTD.	-	PIONEER CRYOGENICS PTY LTD.	1 UNIT	-	n/a	n/a	17-Sep-13	18-Oct-13	-	X	X	-
57-0167	Repairing of vaccum Jacket Vessel	LINDE (THAILAND) PUBLIC CO., LTD.	-	LINDE (THAILAND) PUBLIC CO., LTD.	4 UNITS	11.77	SA240 T304	n/a	08-Apr-14	15-Sep-14	-	X	X	-
57-0190	Repairing of vaccum jacket vessel (VCS 1500 NC)	LINDE (THAILAND) PUBLIC CO., LTD.	TANK REFURBISHMENT (MAJOR DEFECT-INNER LEAK) PROJECT	LINDE (THAILAND) PUBLIC CO., LTD.	1 UNIT	3.87	A36/SA353	n/a	03-Sep-14	-	-	X	X	-
57-0195	Repairing of Vaccum Jacket(VCS 3000NP)	LINDE (THAILAND) PUBLIC CO.,LTD.	TANK REFURBISHMENT (MAJOR DEFECT-INNER LEAK) PROJECT	LINDE (THAILAND) PUBLIC CO.,LTD.	2 UNITS	20.22	n/a	n/a	10-Sep-14	-	-	X	X	X